

Upper Church Beck Pond (view from left Bank)



CHU_00865 – Weir Structure from pond



CHU_00770 – Brick arched footbridge (upstream face)



CHU_00770 – Brick arched footbridge (downstream face)



CHU_00682 – Channel Section (upstream view)



CHU_00682 – Channel Section (downstream view)



CHU_00662 – Channel Section (upstream view)



CHU_00662 – Channel Section (downstream view)



CHU_00550 – Wooden Footbridge (upstream view)



CHU_00550 – Wooden Footbridge (downstream view)



CHU_00458 – Toad Cottage culvert inlet



CHU_00443 – Toad Cottage culvert outlet



CHU_00427 – Weir/Bridge Structure at Church Becks Cottage (upstream view)



CHU_00427 – Weir/Bridge Structure at Church Becks Cottage (down stream view)



CHU_00423 – Carr Lane twin arched culvert inlet



CHU_00423 – Carr Lane twin arched culvert outlet



CHU_00378 – Channel section (upstream view)



CHU_00378 – Channel section (downstream view)



CHU_00343 – Twin arched bridge (upstream face)



CHU_00337 – Twin arched bridge (downstream face)



CHU_00328 – Channel Section (upstream view)



CHU_00328 – Channel Section (downstream view)



CHU_00282 – Wooden Footbridge (downstream view)



CHU_00282 – Wooden Footbridge (downstream view up close)



CHU_00242 – Channel Section (upstream view)



CHU_00242 – Channel Section (downstream view)



CHU_00190 – Channel Section (upstream view)



CHU_00190 – Channel Section (downstream view)



CHU_00125 – Channel Section (upstream view)



CHU_00125 – Channel Section (downstream view)



Appendix B: Photographic Record

CHU_00075 – Channel Section (upstream view)



CHU_00075 – Channel Section (downstream view)



CHU_00020 – Upstream face of outfall into Sea Cut (Scalby Beck)



COL_00016 – Upstream face of driveway b ridge



COL_00009 – Downstream face of driveway bridge

