

Appendix C – Photographs

The following photographs show the general setting of North Bay, Scarborough and the coastal defence assets.



Aerial view of North Bay looking south towards Castle Headland. The Sands development (white high rise curved apartment buildings) is visible approximately halfway along the frontage; this marks the boundary between the North Bay Cliffs Management Unit and the Clarence Gardens Management Unit.



Aerial view of North Bay looking north-west across the Castle Headland. The Sands development is again visible approximately halfway along the frontage, along with the Sea Life Centre (white pyramid buildings towards top right of photo) which is at the northern limit of the North Bay Cliffs Management Unit.



Aerial view of North Bay looking south-west showing alignment of existing coastal defence assets. The Sands development is visible at the boundary between the management units and the Sea Life Centre is visible at the northern end of the study area (bottom right of photo).



Aerial view of Clarence Gardens Management Unit showing proximity of properties at top of cliff and tie in of East Pier, Castle Headland, and the Holms Coast Protection Scheme completed in 2005.



Existing coastal defence assets in the Clarence Gardens Management Unit. Rock revetment of the East Pier, Castle Headland and the Holms Coast Protection Scheme (completed in 2005) is visible in bottom left of photograph. The Sands development (white apartment buildings) which marks the start of the North Bay Cliffs Management Unit is visible in the top right of the photograph.

The following photographs illustrate the range of defects identified for the Phase 2 repair works.



Damage and cracked slab at slipway.



Badly abraded sea wall and previously repaired section.



Copes in poor condition and spalling, also previously repaired cope in shot.



Cracking to deck slabs



Undercutting of sea wall.



Damaged copes at access points.